

TAC-2 Driver

Software Version History

You can download the latest system software for free on the web site below. Installation procedures, possible problems and Frequently Asked Questions are also included.

<http://www.zoom.co.jp/>

Version 2.1.0

- **Released as the following bug fix in October 2016**
 1. Noise is generated when using the Digital Performer 9.

Version 2.0.12

- **Released as the following bug fix in July 2015**
 1. After Mac wakes from sleep mode, the latency of TAC-2/2R becomes longer.

Version 2.0.9

- **Released as the following bug fix in April 2015**
 1. When connecting TAC-2/2R, MacBook Air / MacBook Pro is force-quitted.
 2. Unable to select as output device in “System Preferences”>“Sound”>“Sound Effects”.
 3. Unable to use Plug-in application as a stand-alone mode.

Version 2.0.5

- **Released as the following bug fix in November 2014**
 1. Noise is generated on Mac OS X Yosemite (v10.10).

Version 2.0.0

- **Released as the supported version for TAC-2R in September 2014**

Version 1.0.0

- **Released as the mass production in May 2014**