

TAC-2 Driver Software Version History

You can download the latest system software for free on the web site below.
<http://www.zoom.co.jp/>

Version 2.1.4

- Released as the version supporting macOS Catalina(10.15) in October 2019

Version 2.1.1

- Released as the following bug fix in October 2017
 1. Mac sometimes reboots itself (kernel panic) after returning from sleep mode.

Version 2.1.0

- Released as the following bug fix in October 2016
 1. Noise is generated when using the Digital Performer 9.

Version 2.0.12

- Released as the following bug fix in July 2015
 1. After Mac wakes from sleep mode, the latency of TAC-2/2R becomes longer.

Version 2.0.9

- Released as the following bug fix in April 2015
 1. When connecting TAC-2/2R, MacBook Air / MacBook Pro is force-quitted.
 2. Unable to select as output device in “System Preferences”>“Sound”>“Sound Effects”.
 3. Unable to use Plug-in application as a stand-alone mode.

Version 2.0.5

- Released as the following bug fix in November 2014
 1. Noise is generated on Mac OS X Yosemite (v10.10).

Version 2.0.0

- Released as the supported version for TAC-2R in September 2014

Version 1.0.0

- Released as the mass production in May 2014