

Issues and Workaround:

Guitar Lab editor function cannot be used with G3n/G3Xn/B3n

April 2019

Guitar Lab editor function sometimes cannot be used with G3n/G3Xn/B3n with firmware v2.1.

When you experience this, please revert to the firmware v2.0 to avoid the problem.

We apologize for any inconvenience caused.