

MS-100BT System Firmware Version History

The system firmware version is shown on the display at startup. Installation procedures, possible problems and Frequently Asked Questions are also included.

<http://www.zoom.co.jp/>

Version 1.30

- **Released as following bug fix on July 2013**
 1. Unable to use Bass effects downloaded from StompShare.
 2. When turning power on, effects disappear in rare cases.
 3. MS-100BT fails to update in rare cases.

Version 1.10

- **Released as following bug fix on January 2013**
 1. Unable to switch the signal of specific effects(“Bomber” or “MonoSynth”), when using “LineSel”.
 2. MS-100BT can not start up sometimes when running on batteries.

Version 1.00

- **Released as mass production on November 2012**