

# TAC-8 Driver Software Version History

You can download the latest system software for free on the web site below.  
<http://www.zoom.co.jp/>

---

## Version 1.1.2

- Released as the following bug fix in August 2019
  1. Noise is heard when using DAW on macOS10.14.5.

## Version 1.1.1

- Released as the following bug fix in November 2017
  1. Mac sometimes reboots itself (kernel panic) after returning from sleep mode.

## Version 1.1.0

- Released as the following bug fix in October 2016
  1. Noise is generated when using the Digital Performer 9.

## Version 1.0.3

- Released as the following bug fix in July 2015
  1. After Mac wakes from sleep mode, the latency of TAC-8 becomes longer.

## Version 1.0.1

- Released as the following bug fix in April 2015
  1. When connecting TAC-8, MacBook Air / MacBook Pro is force-quitted.

## Version 1.0.0

- Released as the mass production in January 2015